
Info
The importation process have been failed!
See Info log for more details.
Aceptar
Import epanet inp file
Config
Info log
IMPORT INP EPANET FILE

ERRORS

ERROR-239: There are at least one network id with more than 16 digits. Please check your data before continue
ERROR-239: There are at least one non visual objects (curves & patterns) id with more than 16 digits. Please check your data before continue
WARNINGS

WARNING-239: It seems that inp file not comes from Giswater project. All nodarcs (valves and pumps) will be imported as arc feature
INFO

Run
Close